



3649 Routes 5 and 20 • Canandaigua, NY 14424

**ENGINE • MACHINE • WELDING**

**DRIVESHAFT REPAIR & BALANCING**

www.ontarioengine.com Phone: 585-905-0625

info@ontarioengine.com

<b>Driveshaft Labor Rates</b>	
<b>Description</b>	<b>Price</b>
<b>Assemble PTO Shaft</b>	<b>\$40.00</b>
<b>Weld &amp; Assemble PTO Shaft</b>	<b>\$50.00</b>
<b>Weld &amp; Assemble 1 End 1260-1410</b>	<b>\$65.00</b>
<b>Weld &amp; Assemble 1 End 1480-1550</b>	<b>\$80.00</b>
<b>Weld &amp; Assemble 1 End 1610-1880</b>	<b>\$85.00</b>
<b>Weld &amp; Assemble 2 End 1260-1410</b>	<b>\$85.00</b>
<b>Weld &amp; Assemble 2 End 1480-1550</b>	<b>\$95.00</b>
<b>Weld &amp; Assemble 2 End 1610-1880</b>	<b>\$105.00</b>
<b>Cut Tubing</b>	<b>\$15.00</b>
<b>Assemble CV Joint</b>	<b>\$65.00</b>
<b>Change Customer's U-Joints</b>	<b>\$45.00</b>
<b>Install U-Joint</b>	<b>\$15.00</b>
<b>Install U-Joints PTO Shaft</b>	<b>\$45.00</b>
<b>Balance 1260-1410</b>	<b>\$35.00</b>
<b>Balance 1480-1550</b>	<b>\$45.00</b>
<b>Balance 1610-1880</b>	<b>\$65.00</b>
<b>Balance 2 Piece 1260-1410</b>	<b>\$45.00</b>
<b>Balance 2 Piece 1480-1550</b>	<b>\$55.00</b>
<b>Balance 2 Piece 1610-1880</b>	<b>\$80.00</b>
<b>Replace Carrier Bearing</b>	<b>\$45.00</b>
<b>Job Prices Do Not Include Parts</b>	